


PCE Groundwater Contamination in South Lake Tahoe, CA

Document Path: X:\Projects\General\17W006 So Y FS\Public Outreach\Fact Sheets\So Y FS Public Outreach.mxd



Legend

--- South "Y" Plume (PCE)

Public Supply Well

- ▣ Active
- ▣ Standby
- ▣ Inactive
- ▣ Destroyed

PCE Detected in Well


- ▣ No
- ▣ Yes

WATER SYSTEM

- ▣ Lukins Brothers WC
- ▣ Tahoe Keys WC
- ▣ South Tahoe PUD



1/2018



Content may not reflect National Geographic's current map policy.
Sources: National Geographic, Esri, DeLorme, HERE, UNEP-WCMC, USGS, NASA, ESA, METI, NRCAN, GEBCO, NOAA, increment P Corp.